




**NOTE:** MONOVENTS MAY NOT BE 100% WEATHERTIGHT IN SOME STORM CONDITIONS. CONDENSATION ON VENTS CAN ALSO PRODUCE MOSITURE INFILTRATION OF THE BUILDING SYSTEM.



**ALL VENTS ARE SHIPPED WITH END CAPS REMOVE CAP AND SPLICE AS SHOWN ABOVE FOR CONTINUOUS VENT OPERATION**

**SUGGESTED DIAGRAM FOR INSTALLATION OF OPERATOR CHAIN (PARTS SHOWN NOT SUPPLIED)**

**Monovent Details**